

## **CHANGE HISTORY FOR BDP-V6000**

### **Ver 4.65**

- ✓ Improved play ability of BD and CD

### **Ver 4.24**

- ✓ Fix issue of cannot stop with the address that by RS-232C SM command, PL command.
- ✓ During a search by a RS-232C SL command, it was changed to output a screen before search.
- ✓ Enhances stability of Chapter Repeat

### **Ver 4.13**

- ✓ When address assignment is Time by a RS-232C SE command, the still image has improved the deficiency which slips several frames
- ✓ The deficiency which may be unable to set up power-on start function has been improved.
- ✓ Enhances BD-ROM playability and stability of BD-Java playback
- ✓ Enhances stability of BD-LIVE functions
- ✓ Enhances stability of BD-R/BD-RE playback

### **Ver 4.03**

- ✓ Original version